

Technical Information Cleaner & Degreaser



A mild universal degreaser and cleaner to remove residues of silicone, wax, tar, fat etc. before application of paint. For use on porcelain, glass, acrylic glass, ceramics and blank metals. Evaporates quickly without leaving residues.

Ideally suitable for pre-treatment before colouring cups, plates, mugs or vases and bottles for decorative purpose and everyday use. Improves the colour brilliance and lifetime of the paint.

Quality and properties

- Mild effect
- Universal use
- Removes residues of silicone, wax, tar, fat etc. before application of paint.
- High solvency
- Good degreasing properties
- Leaves no residues
- Non-corrosive

Physical and chemical data

Basis: specific solvents Colour: transparent

Smell: characteristic Storage stability:

10 years if appropriate storage provided (=10°-25°C, relative air humidity of max. 60%)

Size: aerosol cans, maximum nominal volume 150 m

Environment and labelling

Environmentally sound: European Aerosols is committed to apply formulations without restricted or critical ingredients and to achieve best possible performance. The caps and packagings are made of recyclable material.

Disposal: Only the completely emptied cans should be put into the recycling skip or appropriate container for reclaimable refuse. Cans which are not empty should be disposed off as "special refuse".

Marking/Labelling: All products made by European Aerosols comply with the actual labelling regulations according to Preparation Guideline 1999/45/EG. All aerosols correspond to TRGS 200 and TRG 300 as well as to aerosol guideline 75/324/EWG in the actually valid version.

Using instructions

The most DUPLI-COLOR spray paints have a so-called no-spray ring or a tamper-proof cap. This is to avoid unauthorized use. Please see the corresponding advises on the cap or on the label.

Before use, carefully read and observe the warning texts on the label!

Application

- Before spraying bring the can to room temperature
- Test surface for compatibility.
- · Spray on the parts to be cleaned and wipe off with a dry, fatfree and lintfree cloth.

Tips for spray painting

Protect the object and the surrounding area from spray mist. Temperature should range between +10°C and +25°C, max. air humidity 60 %.

Store in a dry place. Protect from direct sunlight and other sources of heat. Use only during dry weather, in places protected from the wind, and in well-ventilated rooms. Follow the warning texts on the labels!

Disclaimer of liability

This application-technological information is given to the best of our knowledge. The notes mentioned herein are, however, non-binding and do not exempt you from own tests to see whether the products supplied by us are sultable for your special application. The use and processing is beyond our control and therefore exclusively in the responsibility of the user. European Aerosols is let off the liability, unless the liability-based incident is caused by a fault incurred to European Aerosols.

As of October 27, 2011

This release replaces all eventually earlier issued versions.

Print date: 19.04.2024

European Aerosols | Wolfraamweg 2 | 8471 XC Wolvega | NL | info-nl@european-aerosols.com